

Part list



				
① x1	② x1	③ x2	④ x1	⑤ x1

Hardware list

					
A x8(M8x25)	B x1 (6mm)	C x1	D x1	E x1 If necessary	F x2

2 of 7


Step 1



	
A x4	B x1


3 of 7

Step 2




4 of 7

Step 3




5 of 7

Step 4



6 of 7

Step 5



7 of 7