


3 Hang the monitor on workstation

# Installation Instruction

**Electric Desktop workstation** 




## **IMPORTANT SAFETY INSTRUCTOPNS**

Please read through these instructions

completely to be sure you're comfortable with this easy install process. Also check your Monitor owner's manual to see if there are any special requirements for mounting your Monitor. If you do not understand these instructions or have doubts about the safety of the installation, assembly or use of this product, contact your Customer Service.

### 620x415mm Worksurface Size: 75x75, 100x100 VESA Compatible: 25kgs Weight Capacity: Tilt Range: +10°~-10° +10°~-10° Swivel Range: Screen Rotation: 360° Lifting Range: 425-875mm Lifting Speed: 35mm/s Input Voltage: 110/240V Column Segments:

Memory Data:



# To use your workstation


Press button UP, The column will rise up, and loosen the button, it will stop immediately.

Press button DOWN, The column will down, and loosen the button, it will stop immediately.

The column will stop and back to a safe distance immediately when meet an obstacle.


The panel can be adjusted tilt, swivel and rotation by hand.

The product has motor protection device, please do not press the button UP & DOWN continuously, it needs to wait 3 seconds



### Other function

You can put your phone, tablet, documens and stationery in the slot



The workstation should be far away the corrosivity and dusty environment. The workstation is not waterproof.



Do not obstruct operation of mechanism with fingers or any object. Injury or damage could result. If adjusting the limits, do so prior to wiring into control systems.




Risk of Electrocution:
Do not connect any power to the lift until installation is complete.
Attach the display panel after the lift has been properly installed and







The workstation should be operated under this Instruction Manual.







Check parts and hardware according to instructions





Assembly the desktop workstation





Install the foot pad 7 and tighten it

